

# **Product Discontinuation Notification**

PDN#21-13- The listed KT11 part numbers EOL with replacement

# C&K

Office 1007-8, 10/F, Harcourt House, 39 Gloucester Road, Wanchai, Hong Kong Tel: +852 3713 5288 ckswitches.com

Document subject to change without prior notice



# **Document revision**

Revision	Date	Description	Author
Α	2021/5/13	The listed KT11 part numbers	Daisy Liu
		end of life with replacement	

# C&K

Office 1007-8, 10/F, Harcourt House, 39 Gloucester Road, Wanchai, Hong Kong Tel: +852 3713 5288 ckswitches.com

Document subject to change without prior notice

PDN# 21-13 rev A Page 2/5



# Summary

1.	Purc	DOSE	. 4	
	Discontinuation details			
		Part References affected		
		Possible replacement		
		Reason for discontinuation		
3.	Date	e of application	5	
	Acknowledgement			
		port		



## 1. Purpose

This notification is to announce the discontinuation of below listed P/Ns in KT11 series.

#### 2. Discontinuation details

#### 2.1 Part References affected

ITEM NUMBER	CATALOGUE PART NUMBER	Replacement (1)	Replacement (2)
YT1063570FP LFS	KT11P4SA3M34LFS	KT11 <mark>B2</mark> SA <mark>3</mark> M34LFS	KT11P4SA2M34LFS
YT1064770FP LFG	KT11P4SA3M35LFG	KT11B2SA3M35LFG	KT11P4SA2M35LFG
YT1064770FPLFGM	KT11 <b>P4</b> SA3M35LFG-M	KT11B2SA3M35LFG-M	KT11 <b>P4</b> SA2M35LFG-M

# 2.2 Possible replacement


Refer to 2.1

# 2.3 Reason for discontinuation

With the world's widest selection of switch products it is critical that we keep our Portfolio current and relevant to our customers. The above listed part numbers P4SA3M combination was created for some special customer demands some years ago but where not in our catalogue, so they are not as popular as our standard parts. As such they are no longer commercially viable to produce and will be EOL with replacement 2 possible close alternatives:

#### Close Alternative (1): Same layout but different actuator.

The difference between the P4SA3M version and replacement(1) B2SA3M version is: P4 version is hard actuator 3.96mm, while the B2 version is the soft actuator 2.24mm.



### C&K


Office 1007-8, 10/F, Harcourt House, 39 Gloucester Road, Wanchai, Hong Kong Tel: +852 3713 5288 ckswitches.com

Document subject to change without prior notice

PDN# 21-13 rev A Page 4/5



Close Alternative (2) Same actuator but different TAB with request more space on the PCB The difference between the P4SA3M version and replacement(2) P4SA2M version is: P4SA3M version does not have a front solder pad, while the P4SA2M version has a front solder pad which



# 3. Date of application

Last Time Buy: 30<sup>th</sup> Nov, 2021

Last Delivery: 30<sup>th</sup> May, 2022

Date of Discontinuation: 30<sup>th</sup> May, 2022

### 4. Acknowledgement

We kindly ask you to acknowledge this information to your Sales Representative.

# 5. Support

For any question, please contact your C&K regional sales representative.

### C&K

Office 1007-8, 10/F, Harcourt House, 39 Gloucester Road, Wanchai, Hong Kong Tel: +852 3713 5288 ckswitches.com

Document subject to change without prior notice

PDN# 21-13 rev A Page 5/5